

How to check that a device tree resource is correctly set

Stable: 19.02.2019 - 17:25 / Revision: 30.01.2019 - 19:31

Refer to [UART issue scenario](#) which provides examples for checking:

- Linux kernel driver probe
- Pins configuration
- Clocks configuration
- Interrupts configuration